

ZCZCSPQ022

DAN: 472-011070

INPUT CDSN: DK1491

BFN: PA021946

TOR: 021956Z FEB 87

TOT: 021956Z FEB 87

ROUTING= DPG

WIRE SVC= **UNASSIGNED**

COMMDIS=**UNASSIGNED**

RTTUZYUW RUEOGFA0203 0331949-UUUU--RUTLAAB.

ZNR UUUUU ZYN ZPD

R 021946Z FEB 87

FM FBIS PM

STAT

TO RUTLAAB/FBIS WASHINGTON DC

ACCT FBPA-EWDX

BT

UNCLAS

ATTN

STAT

ONLY FSB/FED

SUBJ

SERVICE: INTERNET EQUIPMENT

PA021946

INSPECTED THE INTERNET EQUIPMENT TODAY AND EXCEPT FOR THE
PERSISTENT UPS ALARM EVERYTHING IS OK, INCLUDING THE AIR
CONDITIONING SYSTEM. APPARENTLY THE RELAY THAT WAS CAUSING THE
PROBLEM IS BEGINNING TO WORK PROPERLY AFTER AN INITIAL
BREAK-IN PERIOD. REGARDS. 021952Z FEB

STAT

BT

#0203

NNNN